

SITE SURVEY REPORT

Lifting Accessory Pre-use Inspection

Prepared for	Airedale Mechanical Services Ltd
Date	30 Sep 2026
Site	Kirkgate Mill, Bradford
Prepared by	T. Nwosu

FORM

Lifting Accessory Pre-use Inspection**1. Record details and scope**

Project	Kirkgate Mill, Bradford: chiller replacement lift
Site or premises address	Kirkgate Mill, Canal Road, Bradford
Client or organisation	Airedale Mechanical Services Ltd
Record date	30 Sep 2026
Person completing the record	T. Nwosu, slinger signaller

For trained users following accessory-specific instructions. This is not a LOLER thorough examination, load test, lift plan or calculation of sling capacity.

HSE distinguishes routine checks from thorough examination of lifting accessories. Markings, suitability and examination arrangements need to be appropriate to the equipment and use; a pre-use record does not replace them.

2. Lift and inspection scope

Lift or task reference	Lift plan LP-KM-009, chiller unit from the lorry to the roof plant deck
Trained user and authorisation reference	T. Nwosu, slinger signaller card checked, authorisation AMS-SS-12
Manufacturer or inspection procedure reference	Makers' instructions for each accessory and company sheet AMS-LA-01
Scope and inaccessible features	Visual and touch check only. Internal wear on shackle pins not checked without stripping.

3. Accessory records**Lifting accessory 1: CS-221, four leg chain sling**

Unique ID and accessory type	CS-221, four leg chain sling
Marked working load limit and configuration information	WLL marked on the tag for each angle range, 0 to 45 and 45 to 60 degrees
Current examination report reference	Thorough examination TE-CS221-0726
Condition against the manufacturer checks	Links, hooks and safety catches checked along each leg. No stretch, nicks or twisting. Tag readable.
Pre-use outcome	No defect identified within scope

Lifting accessory 2: WS-118, 3 m round sling

Unique ID and accessory type	WS-118, 3 m round sling
Marked working load limit and configuration information	WLL marked on the label, straight and choke
Current examination report reference	Thorough examination TE-WS-0826
Condition against the manufacturer checks	Cut on the outer cover about 20 mm long near the eye. Inner yarns not seen but the cover is broken.
Pre-use outcome	Quarantine
Defect, quarantine identification and person informed	Red tag Q-0930-1 fitted and sling put in the quarantine bin in the container. Told the lifting supervisor, A. Shah.

Supporting photos**Lifting accessory 3: SH-401 to SH-404, bow shackles**

Unique ID and accessory type	SH-401 to SH-404, bow shackles
Marked working load limit and configuration information	WLL marked on each body
Current examination report reference	Thorough examination TE-SH-0826
Condition against the manufacturer checks	Pins fully in and threads clean. No bending or wear on the bows.
Pre-use outcome	No defect identified within scope

4. Handover

Separate lift-planning and compatibility checks referenced	Slings and shackles checked against the lift plan LP-KM-009 by the appointed person. Spare round sling WS-122 used in place of WS-118.
--	--

Storage and protection after use	Slings hung in the lifting store container, off the ground and out of the weather. Shackles in their box.
Supervisor or next user informed	A. Shah, lifting supervisor, told at 07:45

5. Actions and review

Are further actions required?	Yes
-------------------------------	-----

Further action 1: Send round sling WS-118 back to the supplier for disposal and record it on the register.

Action and evidence reference	Send round sling WS-118 back to the supplier for disposal and record it on the register.
Person responsible	A. Shah, lifting supervisor
Target date	3 Oct 2026
Action status	Open
Outstanding limitations and information to pass on	Round sling WS-118 quarantined. Shackle pins not stripped.
Record status	Ready for review
Reviewed by	A. Shah, lifting supervisor
Review date	30 Sep 2026
Author signature	

T. NWOSU

Signing records the information entered. It does not itself certify legal compliance, remove a limitation or authorise unsafe work.