

SITE SURVEY REPORT

Pre-delivery Inspection

Prepared for	Coast Plumbing Ltd
Date	8 Oct 2026
Site	Van PDI
Prepared by	K. Shaw

FORM

Pre-delivery Inspection

1. Item

Project	Van PDI: Mercedes-Benz Sprinter for Coast Plumbing (completed example)
Client	Coast Plumbing Ltd
Site	Harbour Commercials
Site address	Unit 6, Harbour Way, Poole
Inspection date	8 Oct 2026
Time	11:00
Inspected by	K. Shaw, workshop
What is being delivered	Car or van
Make and model	Mercedes-Benz Sprinter 315 L2H2 panel van
Serial number, VIN or registration	WDB9076331P000123
Hours or mileage	12
Has an open recall check been done?	Yes

2. Checks

Bodywork, paint and trim	Defect
What is wrong?	Shallow dent low on the nearside rear door from transport, about 280 mm across, paint unbroken.
Glass and mirrors	OK
Tyres and wheels	OK
Lowest tread depth measured (mm)	7.8
Against 1.6 mm	At or above 1.6 mm
Lights and indicators	OK
Fluid levels and leaks	OK
Battery and charging	OK
Controls and instruments	OK

Safety devices, guards and interlocks OK

Warning labels and decals OK

Function test OK

Photos of any defects



Illustrative stamp: 8 Oct 2026
09:15 BST · sample GPS 51.5074,
-0.1278. Original photo capture
date/location unverified.

Largest defect length (mm) 280

Largest defect length (mm): measuring photo



Checks OK 9

Defects 1

Not applicable 0

3. Handover

Supplied with the item Keys, Manuals, Service book, Accessories ordered

Was the customer shown how to use it? Yes

Photos at delivery



Handover location (GPS) Coast Plumbing yard, Holes Bay Road · 50.708150, -1.991720 (SZ 00680 89834, ±9 m)

Result Delivered with agreed defects to fix

Defects agreed and when they will be fixed Smart repair to the nearside rear door dent booked for 15 October at our cost.

Customer name G. Rowe, Coast Plumbing

Customer signature

G. Rowe, Coast Plumbing

Completed by K. Shaw

Signature

K. Shaw